

Road Inspection Form

File ID	Local Name	Stratum	From - To KM	Current State	Risk	Inspection Frequency
7458-01	Adams West	1	0.000 - 81.157	Industrial	Medium	2

Inspection Date	Inspection Number	Reason for Inspection	Method	Inspected By
2026-03-15	125-10	annual	field visit	Bailey

Notes
Annual inspection to confirm compliance items & that the obligation to maintain this road is being met.

Compliance

Signs	
Road	Yes
Road Freq.	Yes
KM Markers	Yes
Stop/Yield	Yes

Hazards	
Brushing	N/A
Danger Trees	No
Sightlines	Yes
Pullouts	Yes

Road Surface	
Running	Yes
Road Prism Stab.	Yes
Depth of Surfacing	Yes
Erosion	No

Drainage	
Natural	Yes
Drainage Struct.	Yes
X-Drains	Yes
Ditches	Yes
Culverts	N/A

Structural Integrity	
Adequate Ballast	Yes
No Washouts	Yes
No Tension Cracks	Yes
Cut & Fill Slopes	N/A

Bridge	
Running Surface	Yes
Delineators	Yes
Guard Rails	Yes

Problems Identified

Problem	From - To KM	Distance	Maintenance Recommended	Urgency	Date
Washboard areas	0.000 - 21.500	21.500	Regular grader maintenance	L	2026-03-13


Notes:					
Washout	50.000 - 51.500	1.500	Culvert installation	H	2026-03-15

Notes: Field crew set out Hazard warning signs set on either side of the washout. Notified roads supervisor

Photos

Longitude	Latitude	Altitude	Date
-113.8658104	53.5543600	671.7999878	2026-03-15 00:00:00

Notes:

Longitude	Latitude	Altitude	Date
<p>Date/Time: Sun 2026-03-15 16:52:33 Longitude: -113.8658104 Latitude: 53.55436 Altitude: 671.79999 Heading: Datum: WGS-84</p>  A photograph showing a dirt road that has been cleared through a forest. The road is light brown and appears to be a single-track or narrow road. The surrounding area is a mix of cleared land with exposed soil and some remaining trees. In the background, there are rolling hills or mountains under a cloudy sky. The overall scene suggests a logging or land-clearing operation in a mountainous region.			